

**SECRET**

Declassification Review by NGA/DoD

00756383

S E C R E T 062148Z

1965 AUG 6 21 53Z

25X1

1. CAMERA B 7 WAS USED IN MISSION 8035 FLOWN ON 4 AUGUST 1965.  
PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

## 2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: EDGE STATIC IS PRESENT ON THE OUTBOARD EDGE OF THE FILM. MANUFACTURER'S SPLICES ARE LOCATED IN FRAMES 308 AND 1573. A HEAT SPLICE IS LOCATED IN FRAME 1094 AND BETWEEN FRAMES 6/7, 12/13, 29/30, 47/48, 56/57, 63/64, 104/105, 1153/1154, 1930/1931 AND 2009/2010.

C. 9L SIDE: THE IMAGE OF A MANUFACTURER'S SPLICE APPEARS IN FRAME 257. MANUFACTURER'S SPLICES ARE LOCATED IN FRAMES 260 AND 1528. THERE ARE NUMEROUS EMULSION LIFTS AND GOUGES IN FRAMES 1094 AND 1095. HEAT SPLICES ARE PRESENT IN FRAMES 1095 AND BETWEEN FRAMES 1212/1213. CREASES OCCUR IN FRAME 1211 AND ALONG THE INBOARD EDGE OF FRAMES 1529/1530.

D. BOTH SIDES: ROLLER CHATTER IS PRESENT ALONG THE INBOARD EDGE. IRREGULAR PLUS DENSITY STREAKS APPEAR INTERMITTENTLY THROUGHOUT THE MISSION. THE LAST TITLED FRAME OF THE MISSION IS 2216.

## 3. POSITIVE:

A. PI SUITABILITY IS GOOD WHERE NOT DEGRADED BY CLOUDS OR ATMOSPHERICS.

B. PRINTING AND PROCESSING WAS GOOD.

C. APPROXIMATELY 60 PERCENT OF THE COVERAGE WAS CLOUD COVERED.

S E C R E T

//END OF MESSAGE//

**SECRET**

09 AUG 1965

COPIES RECEIVED		
By No.	Using	Act.
1	File	
2	OS	
	ADMIN	
	SEC BR	
	F&DS	
	CCD	
	IPD	
	PD	
	P&D	
3,4	P&D-ICB	
	TID	
	PID	
	PAI	
	DIAXX 4	
	SPAD	

25X1  
25X1